HL01F05 – SHE Lessons Learned



Protection of Above Ground Services			
Authorised by:	James Dobson	Date: August, 2016	
Distribution:	eight₂O and Contractors - TW Health & Safety Hub		

Crash Deck protecting Biogas pipe Hogsmill STW



What Happened?

- A section of shuttering was being lifted when an ancillary item detached from the shutter.
- The team had planned for the probable eventuality and erected a rash deck to protect pipe work and the process.

What Happened?

- Road plates were being moved for temporary storage on site.
- When both plates came in contact (metal on metal) the top road plate slid down the small bank towards three cables which had been previously excavated by the site team.
- The road plate damaged the outer core of one of the data cables.
- All three were placed above ground and marked with yellow electrical tape.

Data Cable Damaged Highworth STW



What can we do to prevent this from happening again?

- Planning in advance to eliminate the risk of hitting an above cable / service or injuring an operative;
- All lifting operations should be properly planned and briefed to all involved;
- Ensure suitable laydown areas are considered for the storage of materials on site;
- Ensure that additional controls are put in place for the protection of above ground services;
- Site management to set expectations and reinforce the importance of everyone being aware of their surroundings and the potential hazards they face;
- Review all services to understand the potential impact SHE and operational impact of a service strike:
- Mitigation and recovery plans should be detailed in the RAMS or CPP.

HL01F05 - SHE Lessons Learned



We the undersigned have been made aware of the contents of this briefing. If we are unable to carry out the work safely or if the environment is at risk, we agree that we must immediately stop work and inform our manager/supervisor.

Date	Name	Signature
Manager/supervisor's signature:		Date: