

IA Team Standdown

14th June 2016

Outline of Incident on 9th June 2016

- Incident occurred outside of 5 Warren Street at 10:30 A.M
- Team were excavating in the footway when they struck an LV service cable resulting in two of our colleagues in need of hospital treatment, one for shock and the other for flash burns
- We are pleased to say that the burns are not as severe as first thought and both of our colleagues are expected to make a full recovery

PPE

- The PPE worn during the incident all worked as designed.
- No burns to legs or chest due to the flame and arc resistant clothing.
- LEP protected the eyes of both operatives
- As we approach summer, do not be tempted to roll or pull up sleeves
- Gloves are to be worn at all times

PPE

The Shirt took the brunt of the flash. No damage to the inside of the shirt



Minimum Personal Protective Equipment

Hard hat

Task-appropriate eye protection (minimum light eye protection)

Orange high visibility clothing (arc-resistant if dig team)

Arc resistant trousers for Dig Teams


Safety footwear (toe and mid-sole protection)

Task-appropriate gloves

CAT & Genny

- Ensure that CAT & Genny is used before and during dig to locate all services in the area
- Ensure that a full scan of the area is completed including scanning through the excavation to locate any services that may effect your excavation
- Consult drawings before and after scanning area to ensure that all services in the area have been located
- Clearing mark all services and take a photo on SWIMS before dig commences
- Permit to break ground to be completed before dig commences and all operatives on site to have signed it

CALM



Always mark up your findings from your scan

Have you signed up to zero compromise?

Every person in the alliance is empowered to say NO and must always take the opportunity to intervene and report any instance where they, or others, are put in danger.



If we can't do it safely – we won't do it at all.